





Revised:

N/A

- 1. You will need to cut each of these cables and connect in accordance with the schematic below
- 2. Solder the wire connections together using appropriate technique and insulate using heat shrink.
- 3. Use a multi meter to test the continuity between connector pins. Resistance should be less than 0.5 ohms.

